

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

April 12, 2007

Anne Mazza, Administrator The Cottages of Meridian at Bridgetower 3173 West Belltower Drive Meridian, ID 83642

License #: RC-802

Dear Ms. Mazza:

On February 21, 2007, a life safety code survey was conducted at The Cottages of Meridian at Bridgetower. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Chris Laumann, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

CHRIS LAUMANN

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

CL/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program

C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

February 23, 2007

Anne Mazza, Administrator The Cottages of Meridian at Bridgetower 3173 West Belltower Drive Meridian, ID 83642

Dear Ms. Mazza:

On February 21, 2007, a life safety code survey was conducted at The Cottages of Meridian at Bridgetower. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 23, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** 02 - BUILDING 2 A. BUILDING B. WING_ 02/21/2007 13R802

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

			ST BELLTOV N, ID 83642	VEK DKIVE	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORMA	FULL.	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
	Initial Comments The facility was found to be in substantic compliance with the fire and life safety requirements of the Rules for Residentia Assisted Living Facilities in Idaho. No codeficiencies were cited during the stand fire/life safety survey conducted on February 2007. The surveyor conducting the survey was Chris Laumann Health Facility Surveyor Facility Fire safety & Construction	al or ore ard ruary 21,	R 000	DEFICIENCY)	
	cility Standards				

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

TF4521

If continuation sheet 1 of 1



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

	A .											
Facility			Physical Address	Phone Number								
Callages of Manistrator			3173 W Contour was	QU3) 228	- Jaan							
Administrator			City	ZIP Code								
Survey Team Leader			Manda Idaho Survey Type	83642								
Survey Team Leader			Survey Type	Survey Date								
Chas Coman			Fre Life Setery	2/21/07								
NON-CORE ISSUES												
ITEM #	RULE# 16.03.22		DESCRIPTION	2. 10 0 20 0 20 0 20 0 20 0 20 0 20 0 20	DATE RESOLVED	BFS USE						
1	625,03,e	No documentation on h	now to respond to emergencies co)		100 000 000 100 000 000 100 000 000						
**			records could not be sound.			48 68 69						
						10.6 (10.00)						
2.	405.01 B	electrical standards/ 3 montipling adaptics without surge proteties										
		rere found d'extraga cords were found in roums 2, 11, 9,										
		and 6 of Horse I, and Rooms 9 and 4 in homse 2.										
>3-7-7						1000-100-100						
3.	415.04	Fire Glarm Sistem dexin	mentation could not be formed s	Shallas he								
	200	5yolan had been son	used within the last year.	3								
4	415.05	Spenher System dexus	unitation could not be found	showingh	⇒							
		System has been son	xiced within the last year.									
						10 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1						
5.	410.02.	Fire doill documentation	and not be found in its entirity	Stowns								
		a minimum padikipation	of one dull fire souft, por g	ual ter								
		Signature of Facility Representative										
		Signature of Facility Representative			Date Signed	رسب						
3/21/07		11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1			271-6	//						